



# **SERVICE MANUAL PRIME INSOLE RIB LAYER**

**MODELS SRMP · SRMPA · SRM · SRMA**

**SERVICE MANUAL**



**WORTHEN INDUSTRIES, INC.**  
3 EAST SPIT BROOK RD.  
NASHUA, N.H. 03060-5783  
PHONE (603) 888-5443  
FAX (603) 888-7945  
EMail: [info@worthenind.com](mailto:info@worthenind.com)

# **SERVICE MANUAL PRIME INSOLE RIB LAYER**

**MODELS SRMP - SRMPA - SRM - SRMA**

If properly maintained, Prime Rib Laying machines will provide trouble-free operations over long periods of time. Being a high production machine, however, parts will wear and have to be replaced or adjustments needed to correct certain malfunctions which may occasionally arise.

This manual lists the typical troubles which might arise, their probable causes(s) and how they can be corrected by your own machine maintenance department without the necessity for calling our representative for service and perhaps experience a delay before he can arrive. Part numbers referred to can be found and identified from the latest parts catalogue for these machine models. Plate numbers of drawings showing the parts referred to, their numbers and locations on the machine are indicated for your convenience.

